

## Southern W. Accident Alert



## **Preventive Practices:**

- ✓ Never perform electrical work without proper qualifications, certification, and training.
- ✓ Ensure that equipment is de-energized, locked out, and tagged before performing electrical work.
- Check for proper grounding of power conductors where required.
- ✓ Use proper equipment (gloves, etc.) when performing electrical work.
- ✓ Comply with the safety rules, such as 30 CFR 77.704-1 (a) and (b), to protect yourself and your fellow miners.

A fatality occurred at a Boone County Surface Mine when a run-away ten wheel service truck crashed through a berm and landed on its side in an impoundment under four feet of water. The driver succumbed to his injuries sixteen days after the accident.



## **Preventive Practices:**

- ✓ Always conduct a pre-operational check to ensure the equipment is in operating condition. Report and correct defects immediately.
- ✓ Be sure equipment is designed and maintained for safe operation on maximum grades.
- ✓ Make sure that preventative maintenance programs are implemented and followed up on.
- ✓ Mine operators must develop and implement effective maintenance programs.